NATIONAL GEODETIC SURVEY PENCIL RUBBING FORM

| Designation: | BALD 2 | PID: | QE2736 |
|-----------------------------|------------------------------------|-------------------|--------------------------------|
| Stamping: | BALD 2 19 9 1 | | |
| | cy: <u>Brass Disk, "Prim ary G</u> | PS Statio | n", from Oregon DOT |
| 71 0 | , | | |
| Location: <u>Boiler Bay</u> | Wayside, Depoe Bay | County: | Lincoln |
| Rubbing By: | John Q. Surveyor | Date: | 31Decem ber 1998 |
| | • | | |
| Agency: | Oregon DOT | Phone: (<u>3</u> | <u>101</u>) <u>713 - 3194</u> |
| Remarks: | e-mailaddress = jgs@o | rdot.gov | |
| | 3 1 | 9 | |
| | | | |

INSTRUCTIONS:

Place the blank form (or other blank paper) over the mark and rub over the entire disk with a pencil. For rod marks, rub only the designation and date stamping from the rim of the aluminum logo cap. If it is impossible to make a rubbing of the mark, or if the rubbing appears indistinct, a sketch and/or photograph may be substituted.

